## IOWA DEPARTMENT OF TRANSPORTATION

To Office Bridges and Structures Date December 1, 2011

Attention All Employees Ref No. 521.1

From Gary Novey

Office Bridges and Structures

Subject Revision of the English 1030A Light Pole Blister Standard.


(CADD M0228)

Electronic copies are available in the following Office of Bridges and Structures standard directory W:\Highway\Bridge\Standards\Bridges and on the Internet:

## http://www.iowadot.gov/bridge/standard.htm

The revised standard is located on the Bridge Web site.

Standard 1030A was revised to locate the 3 inch slot for the conduit in the embedded plate for the bridge lighting blister. The plate detail is shown below with the encircled dimensions that were changed from 5 \(^3/\_4\) inches to 5 \(^1/\_4\) inches.



For any questions, please check with Stuart Nielsen or Thayne Sorenson.

GAN/ssn